

Repair Order

Due: \$4,857.62

Fold Here

Unit 2006 YAMAHA FX FX CRUISER HO
VIN/Serial No:YAMA3399B606

Color:

Keyboard:

Plate:

Odom/Hrs In:0

Out:0

CHECKED COMPRESSION
1-205 PSI
2-205 PSI
3-215 PSI
4-215 PSI

SERVICE: CLEAN HULL(FULL OF OIL/WATER)

REPLACED BATTERY
REPLACE SPARK PLUGS
REPLACE ENGINE OIL/FILTER(X2)
REPLACE AIR FILTER

REPLACED BATTERY LEADS
REPLACED STARTER RELAY ASSY
REPLACED WIRE HARNESS

DIELECTRIC GREASED ALL ELECTRICAL CONNECTIONS

Parts

Part #	Qty	Description	Price	Discount	Total
5GH-13440-71-00	2.00	5GH-13440-70-00	\$23.36	\$0.00	\$46.72
YBT-4W10W-40-LT	8.00	10W 40 MARINE OIL	\$11.99	\$0.00	\$95.92
NGK-CR9EB-01-00	4.00	SPARK PLUG CR9EB	\$7.80	\$0.00	\$31.20
6B6-14451-01-00	1.00	AIR FILTER	\$166.74	\$0.00	\$166.74
6B6-81940-00-00	1.00	STARTER RELAY ASSY	\$152.66	\$0.00	\$152.66
90159-06008-00	2.00	SCREW & WASHER	\$2.55	\$0.00	\$5.10
6D3-82116-00-00	1.00	MINUS WIRE LEAD	\$121.37	\$0.00	\$121.37
66V-82119-00-00	2.00	WIRE LEAD COVER	\$3.88	\$0.00	\$7.76
60E-82117-20-00	1.00	WIRE LEAD	\$128.69	\$0.00	\$128.69
99999-03771-00	1.00	WIRE HARNESS	\$1,858.13	\$0.00	\$1,858.13
913031	1.00	YB16CL-B KIMPEX BATTERY	\$81.99	\$0.00	\$81.99

Parts Subtotal

\$2,696.28

Labor

Description	Hour	Total
SEE LIST	12	\$1,548.00
Labor Subtotal		\$1,548.00
Job Subtotal		\$4,244.28
All Jobs Subtotal:		\$4,244.28
Shop Supplies:		\$92.88
PST - 7.00%:		\$303.60
GST - 5.00%:		\$216.86
Total:		\$4,857.62
Less Deposits:		\$0.00
Total Due:		\$4,857.62

Thank You For Your Business!

NO RETURNS ON ELECTRICAL PARTS!

Signature: _____